

DIAGRAMS

for the


Kodak DirectView CLASSIC/ELITE CR SYSTEM

Service Codes: 5258, 5259



Important

Qualified service personnel must repair this equipment.



H219_0001GC

PLEASE NOTE The information contained herein is based on the experience and knowledge relating to the subject matter gained by Carestream Health, Inc. prior to publication.

No patent license is granted by this information.

Carestream Health, Inc. reserves the right to change this information without notice, and makes no warranty, express or implied, with respect to this information. Carestream Health shall not be liable for any loss or damage, including consequential or special damages, resulting from any use of this information, even if loss or damage is caused by Carestream Health's negligence or other fault.



This equipment includes parts and assemblies sensitive to damage from electrostatic discharge. Use caution to prevent damage during all service procedures.

Table of Contents

Description	Page
Block	3
System Connections	3
Electrical	4
System Overview	4
ERASE AY	5
IMAGE SCAN SYSTEM	6
MINI-MCB BOARD	7
USER INTERFACE	8
Functional	9
Power Distribution	9


[illegible]

DI5258-1 – 07NOV07

Section 2: Electrical


System Overview

TOP LEVEL WIRING DIAGRAM




H219_0006FC_

ERASE AY




219_0001FC_


IMAGE SCAN SYSTEM



H219_0003FC_




USER INTERFACE



H219_0004DC_

Section 3: Functional

Power Distribution



H219_0002FC_

DIAGRAMS

Publication History

Publication Date	Publication No.	ECO No.	Changed Pages	File Name	Notes
07NOV07	DI5258-1	- - -	All	di5258_1.fm	New Publication

DirectView is a trademark of Carestream Health.
Kodak is a trademark of Kodak used under license.